

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2017

Submitted Date:

07/12/2017

Document Number:

666803333

FIELD INSPECTION FORM

Loc ID 334990 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281129	WELL	PR	04/15/2006	GW	045-11402	LAST DANCE 43C-3-792	PR
281130	WELL	PR	02/07/2011	GW	045-11401	LAST DANCE 43A-3-792	PR
281153	WELL	PR	04/10/2006	GW	045-11403	LAST DANCE 33C-3-792	PR

General Comment:

[Witnessing Flowline Abandonment](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Emission Control Device	# 1				
Horizontal Heated Separator	# 3				
Ancillary equipment	# 1	Chemical unit at wellhead			
Plunger Lift	# 3				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		39.475120,-107.674654
Comment: Hooked up to bradenheads					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	4	200 BBLs	STEEL AST		39.476756,-107.647921		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	YES						
Comment:	Bradenhead vales open						
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 281129 Type: WELL API Number: 045-11402 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 281130 Type: WELL API Number: 045-11401 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 281153 Type: WELL API Number: 045-11403 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Ditches	Pass					
		Rip Rap	Pass			
Gravel	Pass					
Seeding	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT