

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2017

Submitted Date:

07/25/2017

Document Number:

666803396**FIELD INSPECTION FORM**

Loc ID 335365	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 12 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265837	WELL	PR	11/01/2012	GW	045-09066	BENZEL 36-4D(P26NWB)	PR
265839	WELL	SI	01/01/2017	GW	045-09068	BENZEL 26-16A(P26NWB)	SI
265840	WELL	PR	11/01/2012	GW	045-09069	BENZEL 26-15A (P26NWB)	PR
265842	WELL	PR	11/01/2012	GW	045-09071	BENZEL 26-15 (P26NWB)	PR
265843	WELL	PR	11/01/2012	GW	045-09072	BENZEL 35-1B (P26NWB)	PR
266230	WELL	PR	11/01/2012	GW	045-09130	BENZEL 35-2 (P26NWB)	PR
266252	WELL	PR	11/01/2012	GW	045-09135	KELL 35-3A (P26NWB)	PR
270234	WELL	PR	11/01/2012	GW	045-09496	BENZEL 26-15A1 (P26NWB)	PR
270235	WELL	PR	11/01/2012	GW	045-09495	BENZEL 35-1A (P26NWB)	PR
270237	WELL	PR	02/20/2013	GW	045-09493	BENZEL 26-15C(P26NWB)	PR
270238	WELL	PR	11/01/2012	GW	045-09492	Benzel 25-13C(P26NWB)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

11

Comment:

Corrective Action:

Date:

Type: Plunger Lift

11

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

0

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Murray, Richard

Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	300 BBLs	STEEL AST		39.491453,-107.737277		
Comment:							
Corrective Action:							Date:
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:							Date:
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities				
Facility ID: 265837	Type: WELL	API Number: 045-09066	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 265839	Type: WELL	API Number: 045-09068	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last production number posted Nov 2016				
Corrective Action:			Date:	
Facility ID: 265840	Type: WELL	API Number: 045-09069	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 265842	Type: WELL	API Number: 045-09071	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 265843	Type: WELL	API Number: 045-09072	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 266230	Type: WELL	API Number: 045-09130	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 266252	Type: WELL	API Number: 045-09135	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 270234	Type: WELL	API Number: 045-09496	Status: PR	Insp. Status: PR

<u>Producing Well</u>			
Comment:	Plunger lift		
Corrective Action:		Date:	
Facility ID: 270235 Type: WELL API Number: 045-09495 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger lift		
Corrective Action:		Date:	
Facility ID: 270237 Type: WELL API Number: 045-09493 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger lift		
Corrective Action:		Date:	
Facility ID: 270238 Type: WELL API Number: 045-09492 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger lift		
Corrective Action:		Date:	

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
Ditches	Pass					
		Culverts	Pass			
Seeding	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT