

Inspection Photos

9/28/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 317730

Inspection Doc. Number: 682502617

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the end of the location, facing northeast. Inspection doc. #682502082 and #675103836 required operator to removed equipment (meter shed) that still remains on the location. Photo shows equipment has not been removed.