

# Inspection Photos

10/18/2017

Operator: DJ RESOURCES INC - 10213

Location ID: 390646

Inspection Doc. Number: 682502701

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: DJ RESOURCES INC - 10213  
Location ID: 390646



**Photo 1:** Photo taken from the south end of the location, facing northeast. Photo shows location is predominantly bare and exposed soil. Previous inspections required operator to perform reclamation. Unable to find evidence that reclamation activities have been conducted.



**Photo 2:** Photo taken from the south end of the location, facing northwest. Photo shows location is predominantly bare and exposed soil. Previous inspections required operator to perform reclamation. Unable to find evidence that reclamation activities have been conducted.



Inspection Photos  
Operator: DJ RESOURCES INC - 10213  
Location ID: 390646



**Photo 3:** Photo taken from the east end of the location. Trash debris that had been noted In previous inspection still remains. Unable to find evidence that reclamation has been conducted.



**Photo 4:** Photo taken from the north end of the location, facing south. Photo shows location is predominantly bare and exposed soil. Previous inspections required operator to perform reclamation. Unable to find evidence that reclamation activities have been conducted.





**Photo 5:** Photo taken from the adjacent reference area. Photo shows vegetation over the reference area.