

Inspection Photos

Location Name: Valcar USX A 3-14

API #: 05-123-24596

Location ID: 306406



Wellhead looking south. Weeds have been taken care of, emergency contact information has been updated, unused container has been removed



Access road from wellhead looking west. Weeds have been taken care of



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Valcar USX A 3-14
API #: 05-123-24596
Location ID: 306406



Battery looking south. Weeds have been taken care of



Battery looking north. Weeds have been taken care of