

Inspection Photos

Location Name: Jones,Walter 1-26

API #: 05-123-10999

Location ID: 319284



Battery and wellhead looking north



2" unused/unmarked steel riser under the stairs to the crude oil tank