

# Stormwater Inspection

November 3, 2017

Operator: PETROSHARE CORPORATION- 10454

Location ID: 322196

Elbert County, CO

NWNW Section 21 T6S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: RUNNING CREEK #11-21

Location ID: 322196



Google Earth aerial imagery taken 6/14/2016 illustrating tank battery location during operations. Two points of discharge were observed during the November 3, 2017 inspection along the northwest and southern location (highlighted in the red circle). Also, the Running Creek well pad to the northeast appeared to have stormwater erosion issues as well but COGCC staff did not inspect the location due to time constraints.

Inspection Photos  
Location Name: RUNNING CREEK #11-21  
Location ID: 322196



**Photo 1.** Photo taken of the Operator sign at location.



**Photo 2.** Photo taken from the southern location, facing East. Sediment discharge from location is occurring along the southern location and no observed BMPs have been implemented to control and manage stormwater erosion along any portion of the location.



Inspection Photos  
Location Name: RUNNING CREEK #11-21  
Location ID: 322196



**Photo 3.** Photo taken from the southern location, facing South. Photo illustrates the area at which stormwater runoff is leaving the southern location.



**Photo 4.** Photo taken from the northwest location, facing East. Gully erosion evident and no observed BMPs have been implemented to control and manage stormwater erosion along any portion of the location.