

Inspection Photos

12/11/2017

Operator: PDC ENERGY INC - 69175

Location ID: 322636

Inspection Doc. Number: 682502935

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 322636



Photo 1: Photo taken from the well location, facing north. Previous inspections required operator to perform compaction alleviation by 7/8/2017 and to perform reclamation (revegetation activities) by 11/15/2017). Photo shows location remains bare and exposed soil, compaction concerns remains. Unable to find evidence that reclamation activities have been conducted.



Photo 2: Photo taken from the well location, facing south. Previous inspections required operator to perform compaction alleviation by 7/8/2017 and to perform reclamation (revegetation activities) by 11/15/2017). Photo shows location access road remains unreclaimed



Photo 3: Photo taken from the access road. Photo shows access road has not been reclaimed.



Photo 4: Photo from previous inspection dated 6/8/2017. Previous inspections required operator to repair subsidence concerns occurring on the former battery location. Photos 4-6 date from 6/8/2017 to 12/11/2017 show subsidence has not been repaired and degradation has continued, and hole has expanded. 6 foot measuring stick for reference.



Photo 5: Photo taken from inspection dated 8/17/2017. See comments under photo 4.



Photo 6: Photo dated 12/11/2017. Photo shows subsidence has not been repaired, and has been allowed to continue to expand. 6 foot measuring stick for reference.