



## Form Information


Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 9, 2018 3:26:49 PM MST
Server Receive Date:	Jan 9, 2018 3:26:55 PM MST
Reference Number:	20180109-1871588286
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Jan 9, 2018 3:26:14 PM MST [ <a href="#">View Map</a> ]

## Information

Name	reclamationtablet
Date	Jan 9, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NE Team
Well Name	FRENCH GAS UNIT 01-09U FT 1
API Number	50670656300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Completed work description

mowed weeds inside equipment fence