

Inspection Photos
Location Name: Adams #1
API: 05-123-12295



Photo 1: Location, looking NE



Photo 2: Location, looking N

Inspection Photos
Location Name: Adams #1
API: 05-123-12295



Photo 3: Unused, unmarked risers NE of separator



Photo 4: Unused, unmarked risers N of separator.