

# *Inspection Photos*

*API#071-06405*

*Operator: Timber Creek*

*Inspection Number: 680102757*

*Inspection Date: 3/7/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to North.

March 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06405





Photo#2:  
Overview of Location to South.

March 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06405





Photo#3:  
Overview of Location to East.

March 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06405





Photo#4:  
Overview of Location to West.

March 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06405





Photo#5:  
View of unreclaimed fill slope.

March 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06405