Inspector Name: GRANAHAN, KYLE

FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date: 03/28/2018
Submitted Date:

Document Number: 689500686

03/30/2018

FIELD INSPECTION FORM

Loc ID	'		Inspection			Summary: S IS A FOLLOW UP INSPECTION			
315298 Operator In	GRANAHAN, KY formation:	<u></u>	2A Doc Num:		FOL	LOW UP INSPECTION REQUIRED			
		0539		NO FOLLOW UP INSPECTION REQUIRED Findings:					
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP Address: 1125 ESCALANTE DR						7 Number of Comments 0 Number of Corrective Actions			
City:	RANGELY S	State: CO	Zip: _	81648	Corr	ective Action Response Requested			
Contact Info	ormation:								
Contact Name Phone		Phone	Email		С	omment			
Rob Bleil		970-290-2912	rbleil@uta	ahgascorp.com					
Inspected F	acilities:								

Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230583	WELL	PR	11/05/1978	GW	103-08251	FEDERAL 7-18-2-101-S	PR

General Comment:

On location to conduct routine inspection

Inspector Name: GRANAHAN, KYLE **Location** Overall Good: 🔽 Signs/Marker: Type WELLHEAD Comment: present/complete Corrective Action: Date:

Type	BATTERY							
	Present/complete							
Corrective Action:						:		
	Corrective Action: Date:							
	Number: t: 970-693-6021							
Corrective Action:					Date:			
Overall Good: 🔀								
Spills:								
Туре	Area	Volume						
In Containment: N	No							
Comment:								
Multilple Spills	and Releases?							
Equipment:						corrective date		
Type: Ancillary equip	ment #	1						
Comment: chem tote with containment								
Corrective Action:					Date:			
Type: Deadman # & Marked # 4								
Comment:								
Corrective Action					Date:			
Type: Gas Meter Rur	1 #	1						
Comment								
Corrective Action	:				Date:			
Venting:								
Yes/No	NO							
Comment:								
Corrective Action:					Date:			
Flaring:				I				
Type								
Comment:								
Corrective Action:					Date:			

Inspector Name: GRANAHAN, KYLE

·				Inspecte	d Facilities				
Facility ID: _	230583	Type: _	WELL	API Number:	103-08251	Status: _	PR	Insp. Status:	PR
	Producing Well								
	L	PR via natural	lift, no leaks/ve	enting				Detect	
Corrective	e Action:							Date:	

Inspector Name: GRANAHAN, KYLE

	Reclamation - Storm Water - Pit							
Storm Water:								
	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment		
Compaction	Pass							
Comment:	No sediment f							
Corrective Action:								
Pits: NO SURFACE INDICATION OF PIT								

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
689500696	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4421055

Date Run: 3/30/2018 Doc [#689500686]