


Location Name: Pioneer Sunset 24-3
Location 308516



Location Sign on Meter House



Equipment on location and Pit

Inspection Photos

Location Name: Pioneer Sunset 24-3
Location 308516

Calibration Report

Report Date: 24-4-17 12:48 PM
Device ID: 101108108
Location: Pioneer Sunset 24-3
Collection Time: 5/14/17 12:59 PM
Contact: #718-442-7008
System: Pioneer Sunset
Field: Pioneer Natural Resources
Production: Pioneer Natural Resources
Preparation: Pioneer Natural Resources
Specific Gravity: 0.827

Inspection Items:

Item	Yes	No
Pipe Size	<input type="checkbox"/>	<input type="checkbox"/>
Pressure Base	<input type="checkbox"/>	<input type="checkbox"/>
Edges Sharp?	<input type="checkbox"/>	<input type="checkbox"/>
Seal Ring Damaged?	<input type="checkbox"/>	<input type="checkbox"/>

Temperature Base: 11.55
Pressure Base: 11.55
Temperature Base: 11.55
Pressure Base: 11.55

DEFLECTION:

DEFLECTION	LEFT	RIGHT
0.00	0.00	0.00
25.00	25.00	25.00
50.00	50.00	50.00
75.00	75.00	75.00
100.00	100.00	100.00

TEMPERATURE:

TEMPERATURE	LEFT	RIGHT
0.00	0.00	0.00
25.00	25.00	25.00
50.00	50.00	50.00
75.00	75.00	75.00
100.00	100.00	100.00

CanAm Hwy
Google

SAMSUNG-SM-G930V
24-4-17 12:48 PM
Latitude: 37.4038654
Longitude: -104.6207157
CanAm Hwy, Colorado, USA

Calibration Record

