


Inspection Photos  
Location Name: Pioneer Linda T32-3  
Location 308553





Location Sign on Meter House



Equipment on location and unused sound walls and polls

Inspection Photos  
Location Name: Pioneer Linda T 32-3  
Location 308553



Ground Erosion