

Inspection Photos
Location Name: Tillie #1-3
Location ID: 331254



Photo 1: Location, looking NE



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Tillie #1-3
Location ID: 331254



Photo from prior inspection for comparison



Photo 3: Weeds controlled

Inspection Photos
Location Name: Tillie #1-3
Location ID: 331254



Photo from prior inspection for comparison



Photo 4: Weeds controlled along lease road.

Inspection Photos
Location Name: Tillie #1-3
Location ID: 331254



Photo from prior inspection for comparison



Photo 5: Weeds controlled along lease road.

Inspection Photos
Location Name: Tillie #1-3
Location ID: 331254



Photo from prior inspection for comparison



Photo 6: Berms built up

Inspection Photos
Location Name: Tillie #1-3
Location ID: 331254



Photo 7: Stained soil adjacent to treater.



Photo 8: Marked, plugged risers at tank.