

Inspection Photos

API#077-08193

Operator: Caerus

Inspection Number: 674104456

Inspection Date: 5/31/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry to Northwest

May 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Wissel API#077-08193



Photo#2:

Vegetation across Interim Reclamation areas appears sparse and infested with B list Noxious Weed, Dalmatian Toadflax & C list, Field bindweed.

May 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Wissel API#077-08193



Photo#3:
Dalmatian Toadflax & Bindweed is also established along Access Road.



Photo#4:

May 31, 2018