

Final Reclamation and Stormwater Inspection

June 7, 2018

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 336511

Inspection Document #: 674902186

Weld County, CO

NENE Section 26 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W26

Location ID: 336511



Photo 1. Photo taken from the well location, facing North. Appears the Operator has performed reclamation activities with all equipment removed. Gravel remains on the location which has not been decompacted.



Photo 2. Photo taken from the well location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W26

Location ID: 336511



Photo 3. Photo taken from the facility, facing South. A List B Colorado Noxious weed species, Canada thistle (*Cirsium arvense*), is found at low densities at the well site .



Photo 4. Photo taken showing the tank battery location, facing West. See comments from Photo 1.