

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



FIR RESOLUTION FORM

CA Summary:
4 of 5 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com
Ghan, Scott	970-744-8128	sghan@vnrenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689301065
Inspection Date: 05/07/2018 FIR Submit Date: 05/07/2018 FIR Status:

Inspected Operator Information:

Company Name: VANGUARD OPERATING LLC Company Number: 10531
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 334708

Location Name: MILLER-67S91W Number: 6SESW County: GARFIELD
Qtrqtr: SESW Sec: 6 Twp: 7S Range: 91W Meridian: 6
Latitude: 39.469813 Longitude: -107.599549

FACILITY - API Number: 05-045-00 Facility ID: 290402

Facility Name: MILLER Number: 14D-6-791
Qtrqtr: SESW Sec: 6 Twp: 7S Range: 91W Meridian: 6
Latitude: 39.469813 Longitude: -107.599549

CORRECTIVE ACTIONS:

1 CA# 116243

Corrective Action: Date: 05/07/2018

Response: CA COMPLETED Date of Completion: 05/09/2018

Operator Comment: No details listed, but we are assuming this is regarding the note about faded sign on methanol tank. This was list as a CA (in red) in the inspection report. Sign has been replaced.

COGCC Decision: Approved

COGCC Representative: Approval/passing of the Form 4 / FIRR acknowledges that the Oil and Gas Conservation Commission has received the Notice. A field inspection will be conducted to evaluate compliance.

2 CA# 116244

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Date: 05/14/2018

Response: CA COMPLETED Date of Completion: 05/11/2018

Operator Comment: Securely fastened all valves and piping.

COGCC Decision: Approved

COGCC Representative: Approval/passing of the Form 4 / FIRR acknowledges that the Oil and Gas Conservation Commission has received the Notice. A field inspection will be conducted to evaluate compliance.

3 CA# 116245

Corrective Action: Install sign to comply with Rule 210.e. Date: 06/07/2018

Response: CA COMPLETED Date of Completion: 05/13/2018

Operator Comment: Replaced signage as needed.

COGCC Decision: Approved

COGCC Representative: Approval/passing of the Form 4 / FIRR acknowledges that the Oil and Gas Conservation Commission has received the Notice. A field inspection will be conducted to evaluate compliance.

5 CA# 116247

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e. Date: 06/06/2018

Response: CA COMPLETED Date of Completion: 05/11/2018

Operator Comment: Stained areas inside lined secondary containment have been removed.

COGCC Decision: Approved

COGCC Representative: Approval/passing of the Form 4 / FIRR acknowledges that the Oil and Gas Conservation Commission has received the Notice. A field inspection will be conducted to evaluate compliance.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Ghan Signed: _____

Title: Senior EHS Specialist Date: 5/16/2018 8:47:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401641889	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files