

# *Inspection Photos*

*Loc#419862*

*Operator: Terra*

*Inspection Number: 674104548*

*Inspection Date: 7/7/2018*





Photo#1:  
There is heavy senesced Annual Weed Growth in Interim Reclamation as well as growing Russian thistle & Kochia.

July 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#2:

It appears that Interim Reclamation vegetation has largely failed across Location.

July 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#3:  
Delineation between old hayfield and reclaimed area is very visible

July 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#4:

Delineation between old hayfield and reclaimed area is very visible. New vegetation is very weedy; with Noxious weed growth invading into established hayfield.



Photo#5:

July 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#6:  
Old BMP straw bales & staking piled at Southwest side of site have become Debris.

July 7, 2018



Photo#7:  
Weeds along access road.

July 7, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862