

Inspection Photos
Location Name: Beaver Creek 0881 1-3H34
API: 05-057-06602



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Rathole open at wellhead.

Inspection Photos
Location Name: Beaver Creek 0881 1-3H34
API: 05-057-06602



Photo 3. Battery sign with emergency contact information installed at entrance.



Photo 4. Wellhead sign installed.