

Inspection Photos (08-15-2018)

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709




Photo 1.
Location sign

Photo 2.
Fence has been removed from 1 side of the location

Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 3.
Fence and fence posts that were removed from south side of location



Photo 4.
Spoil pile along south side of location.
No storm water BMPs.



Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 5.
Unused equipment



Photo 6.
Open excavation without temporary safety fencing

Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 7.
Open excavation without temporary safety fencing



Photo 8.
Open excavation without temporary safety fencing



Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 9.
Spoil pile without storm-water BMPs



Photo 10.
Spoil Pile without storm-water BMPs



Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 11.
Perimeter fence was removed from south side of location.
Spoil pile without storm-water BMPs.



Photo 12.
Weeds



Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 13.
Sign at tank battery



Photo 14.
Tank battery

Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 15.
Weeds growing inside secondary containment



Photo 16.
Pumpjack

Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 17.
Weeds around pumpjack



Photo 18.
Weeds around pumpjack



Inspection Photos

Location Name: Petroshare Corporation State of Colorado AB

Location ID: 319709



Photo 19.
Weeds around pumpjack



Photo 20.
Weeds around pumpjack

