

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2018

Submitted Date:

08/28/2018

Document Number:

682403915**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 420179 Binschus, Chris 2A Doc Num: _____

Operator Information:OGCC Operator Number: 3250Name of Operator: ANTELOPE ENERGY COMPANY LLCAddress: P O BOX 577City: KIMBALL State: NE Zip: 69145**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Keeler, Jodi	308-235-4661	jodik@antelope-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420177	WELL	PR	02/01/2018	OW	123-32490	State 9-61-16	RI

General Comment:This is a Reclamation Inspection at the battery location.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Operator has failed to control and manage weeds around equipment. Refer to the attached inspection photos.		
Corrective Action:	Comply with Rule 603.f .		Date: 09/11/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 420177 Type: WELL API Number: 123-32490 Status: PR Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682403916	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4563643