

Inspection Photos
Location Name: Malo - 68N59W / 20NESE
Location #: 330637



Photo #1
Malo 9-20 (API # 05-123-19392) Wellhead



Photo #2
Malo 9-20 Battery



Inspection Photos
Location Name: Malo - 68N59W / 20NESE
Location #: 330637



Photo #3
Malo 9-20 Pump jack skid
Unused Equipment



Photo #4
Malo 9-20 H2O vault
Opening may allow animal ingress

Inspection Photos
Location Name: Malo - 68N59W / 20NESE
Location #: 330637



Photo #5
Malo 9-20 Pump jack engine house
Stained soil around engine



Photo #6
Malo 9-20 Pump jack engine house
Stained soil around engine base