

Inspection Photos
Well Name: Oxbow 18-1E
Location ID: 312634



Photo 1. Halogeton, C List Noxious Weed, along access road. No treatment visible at time of inspection.



Photo 2. Halogeton, C List Noxious Weed, along access road. No treatment visible at time of inspection.