

Final Reclamation Inspection

August 31, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-10778

Inspection Document #: 682403958

Weld County, CO

SWNE Section 5 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: THORNTON #1
API: 05-123-10778



Photo 1. Photo taken from the former battery location, facing South. No oil and gas equipment was observed at the location; however, the battery location was not returned back to crop production. Appears the surface owner is now using the battery location for storing farming equipment but there was no final reclamation variance request in the well file.

Inspection Photos
Location Name: THORNTON #1
API: 05-123-10778



Photo 2. Photo taken from the well location, facing West. Well location appears reflective of reference crop areas.



Photo 3. Photo taken from the well location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: THORNTON #1
API: 05-123-10778



Photo 4. Photo taken from the well location, facing East.
See comments under Photo 2.



Photo 5. Photo taken from the well location, facing South.
See comments under Photo 2.