

Inspection Photos
Location Name: GUADAGNOLI #1
Facility ID: 240510



Colorado Oil & Gas Conservation Commission
40.10363, -104.94015, 1506.0m, 120°
2018/09/11 12:48:17

Photo 1. Wellhead



Colorado Oil & Gas Conservation Commission
40.10347, -104.94013, 1486.0m, 160°
2018/09/11 12:48:59

Photo 2. Tank battery

Inspection Photos
Location Name: GUADAGNOLI #1
Facility ID: 240510



Photo 3. Dead weeds near heated separator



Photo 4. Dead weeds near heated separator