

Inspection Photos  
Location Name: May 32-16  
Location ID:320057



Photo 1 WH



Photo 2 TNK BTRY

**Inspection Photos**  
**Location Name: May 32-16**  
**Location ID:320057**



**Photo 3 Stained soil PY motor**



**Photo 4 Stained soil PU exhaust**



**Inspection Photos**  
**Location Name: May 32-16**  
**Location ID:320057**



**Photo 5 Stained soil Load out line back of crude oil tank**



**Photo 6 Stained soil Load out lines in front of crude oil tank**