

Inspection Photos

Loc#452797

Operator: Laramie

Inspection Number: 692400233

Inspection Date: 10/16/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northeast.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#452797



Photo#2:

Failed berm area, indicated by arrow, is located under tongue of equipment trailer .

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#452797



Photo#3:
View from top of Pad of failed BMP area.

Photo#4:
View from base of slope of failed BMP area.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#452797



Photo#5:

Views of fill slope to East of failed area (indicated by arrow) & showing in Photo#6, silt fence overwhelmed by sediment.

October 16, 2018

Photo#6:



Photo#7:
Views of Cuttings storage area along cut slope at East side of Location.
October 16, 2018

Photo#8:
Inspection Photos: Laramie Gunderson Loc#452797



Photo#9:

View over capped drain outlet at Northeast corner of Location. Materials / supplies not stored to minimize contact of precipitation & stormwater. Housekeeping procedures not facilitating clean, orderly operations. Arrow indicates cuttings storage area.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#452797



Photo#10:
Views of stored supplies, materials.

October 16, 2018



Photo#11:



Photo#12:
View of covered storage area.

October 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#452797