

Inspection Photos
Location Name: Elk Springs Unit 4
API: 05-081-06837



Photo 1. Overview of location taken at entrance facing east.

Inspection Photos
Location Name: Elk Springs Unit 4
API: 05-081-06837



Photo 2. 1 of 2 unmarked 1" steel risers in east side of tank battery.



Photo 3. 2 of 2 unmarked 1" steel risers on east side of tank battery.