

Inspection Photo (s)
Pitman 18-2
API # 05-045-06950
Inspection # 689302597



Location Photo #1



Location Photo #2, Holes in containment liner.

Inspection Photo (s)
Pitman 18-2
API # 05-045-06950
Inspection # 689302597



Location Photo #3, Holes in containment liner.



Location Photo #4, Holes in containment liner.