

Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 1


View north at open former oil skim pit excavation



Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 2



Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 3

View west along northern skim pit wall.



Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 4

Clean soil stockpile



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 5 View north at open excavation in the afternoon after additional excavation (PM)

Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 6 View north-notheast at open excavation in the afternoon after additional excavation (PM)



Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 7 Base of excavation (PM)

Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401
Inspection Date: 12/03/2018



Photo # - 8 Impacted soil collected in southwest corner of excavation (PM)

