

Inspection Photos
Location Name: Stroh 35-2
Facility ID: 443097



Photo 1 – General location photo. Monitoring wells within tank berm, site recently located.



Photo 2 – Monitoring wells south of facility

Inspection Photos
Location Name: Stroh 35-2
Facility ID: 443097



Photo 3 – Staining at crude tank access.



Photo 4 – Separator and monitoring wells.