

Inspection Photos
Location Name: WEAVER RIDGE 23-15
Location ID: 05-103-10581
Inspection: 679702474



Photo 1. Location looking east.



Photo 2. Separators and gas meter buildings.

Inspection Photos

Location Name: WEAVER RIDGE 23-15

Location ID: 05-103-10581

Inspection: 679702474



Photo 3. Pump jack and tank battery.



Photo 4. Container at well head without label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: WEAVER RIDGE 23-15
Location ID: 05-103-10581
Inspection: 679702474



Photo 5. Tanks without capacity volume.