

Inspection Photos

Location Name: CONTINENTAL 2-20

Location ID: 05-103-08489

Inspection: 679702697



Photo 1. Location looking northeast.



Photo 2. Well head leaking gas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CONTINENTAL 2-20

Location ID: 05-103-08489

Inspection: 679702697



Photo 3. Tank.



Photo 4. Tank label incomplete. Also need NFPA label and contents.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources