

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2019

Submitted Date:

01/25/2019

Document Number:

689500929

FIELD INSPECTION FORM

Loc ID 332598 Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections
Graber, Candice (Nikki)		candice.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
118846	PIT				-	ARISTOCRAT 32-9 2	EI

General Comment:

COGCC Environmental Inspection to determine the status of pit facility ID 118846. Inspection of pit area only; no nearby battery/production facilities or wells inspected.

The pit status has been changed to closed. However, the operator is instructed to submit a Form 27 for site characterization of the historic pit area.

Inspected Facilities

Facility ID: 118846 Type: PIT API Number: - Status: Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Pit location was determined based on aerial imagery. Distressed vegetation as well as a pit-trace depression is present at the historic pit location.

Corrective Action: Operator shall submit a Form 27 Site Investigation and Remediation Workplan for for the historic pit area. Date: 02/23/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Contact area EPS Nikki Graber with any questions regarding pit status C 970-250-0543 nikki.graber@state.co.us	oakmank	01/25/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401918808	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715534
689500930	ARISTOCRAT 32-9 2 Pit Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715532