

Inspection Photos
Location Name: Sharp #1E
API: 05-067-06330



Location was snow covered during this inspection.



Location sign is illegible.



Inspection Photos
Location Name: Sharp #1E
API: 05-067-06330



Sharp #1E well head.



95 bbl. produced water PBV.