

Inspection Photos

2/27/2019

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 427181

Inspection Doc. Number: 682504548
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 427181



Photo 1: Photo taken from the north end of the location, facing south. Photos 1-3 provide an overview of the interim and production areas of the location from south, southwest to west.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 427181



Photo 2: See comments under photo 1.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 427181



Photo 3: See comments under photo 1.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 427181



Photo 4: Photo taken from the northwest end of the pad, facing southwest. Photo shows operator appears to have traveled off of the designated pad onto the interim areas. This is not compliant with rules 1002.e. Restrict all equipment and vehicle traffic to the constructed pad and designated access road.



Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 427181



Photo 5: Photo taken from the northwest end of the pad, facing south. See comments under photo 4.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 427181



Photo 6: Photo taken from the north end of the pad. Photo shows vegetation on the slopes of the interim area. These areas may require additional seeding to meet reclamation requirements.



Photo 7: See comments under photo 6.



Photo 8: Photo taken from the south end of the location, facing northeast. Photo shows vegetation over the reclamation area.