

Inspection Photos

API: 05-071-06668

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/1/2019

Inspection Photos



Photo 1. Facing northeast toward the location.

Inspection Photos



Photo 3. Facing toward the pit. No freeboard marker was noticed.

Inspection Photos



Photo 2. Facing north toward reclaimed area. Possible offsite pit.