

Inspection Photos  
Location Name: Sylvester F 31-33  
Location ID: 422259



Photo 1: Wellhead



Photo 2: Stained soil at main valve.

**Inspection Photos**  
**Location Name: Slyvester F 31-33**  
**Location ID: 422259**



**Photo 3: Tank Battery**




**Photo 4: No visible securing mechanism on produced water tanks.**

**Inspection Photos**  
**Location Name: Slyvester F 31-33**  
**Location ID: 422259**



**Photo 5: No visible securing mechanism on produced water tanks.**



**Photo 6: Trash inside gas meter house.**