

Inspection Photos

Location Name: J&L FARMS-66N63W /19NENE

Location #: 305231



Photo #1

J&L Farms 41-19 (05-123-22685) Wellsite

Well sign Operator Name NOT posted

from prior FIR



Photo #2

J&L Farms 41-19 Wellsite

Shut-In | SI

Well sign Operator Name NOW posted



Inspection Photos

Location Name: J&L FARMS-66N63W /19NENE

Location #: 305231



Photo #3

J&L Farms 31-19, 41-19 Battery

Shut-down

