

Inspection Photos
Location Name: Noffsinger F 2-5
Location ID: 333063



Photo 1: Wellhead



Photo 2: Appears to be stained soil.

Inspection Photos
Location Name: Noffsinger F 2-5
Location ID: 333063



Photo 3: Centralized Tank Battery



Photo 4: Unused equipment in gas meter house.

Inspection Photos
Location Name: Noffsinger F 2-5
Location ID: 333063



Photo 5: Unused pipe east side of tank battery.



Photo 6: Unused tubing north of gas meter house/separator.