

Construction and Storm Water Inspection

March 28, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC – 10110

Location ID: 452180

Inspection Document #: 674902625

Weld County, CO

NWNW Section 1 T3N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



Photo 1. Photo taken from the northwestern perimeter of the location, facing South. Photo illustrates a compacted BMP that has been installed around parts of the location.



Photo 2. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



Photo 3. Photo taken from the southwestern perimeter of the location, facing East. Photo illustrates the topsoil stockpile being stored along the southern area.



Photo 4. Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



Photo 5. Photo taken from the southeastern perimeter of the location, facing North. See comments from Photo 1.



Photo 6. Photo taken from the eastern perimeter of the location, facing North. The ditch and berm BMP does not go around the entire perimeter of the location.

Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



Photo 7. Photo taken from the northeastern perimeter of the location, facing South. See comments from Photo 6.



Photo 8. Photo taken from the northeastern perimeter of the location, facing West. No silt traps with stabilized outlets were observed on location.