

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Photo at entrance of location

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Wellhead sign

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Tank battery (tanks stored and marked out of service.)



Photos of risers not locked out or tagged

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Unused equipment stored on location



Unused equipment, tanks stored on location

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Unused equipment stored on location.

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Fence down and soil from location pushed off location.

Fence down and soil from location pushed off location.

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Fence down and soil from location pushed off location. Coiled up barbed wire

Laramie Energy LLC
Api # 05-077-08730
Inspection # 675002200



Photos of risers not locked out or tagged



Photos of risers not locked out or tagged