

Inspection Photos

Loc#446582

Operator: Ursa

Inspection Number: 692400908

Inspection Date: 4/16/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#2:
There are no Wildlife escape boards installed in Well Cellars.

Photo#1:
View Northeast along cut slope.

April 16, 2019



Photo#3:
Wash out of ditch & rocked drain has occurred

April 16, 2019



Photo#4:
Wash out of ditch & rocked drain has occurred.





Photo#5:
Sediment moving through perimeter fence,
overwhelming wattles and migrating off site.

April 16, 2019



Photo#6:
Sediment moving through perimeter fence,
overwhelming wattles and migrating off site.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa BMC D Pad Loc#446582