

Inspection Photos
Location Name: Moro Farms CSE-29
Location ID: 419394



Photo 1: Wellhead; Debris needs to be removed. Wellhead sign installed.



Photo 2: Tank Battery