

Inspection Photos
Location Name: Peterson Ridge 1-20H
API: 05-057-06515



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Peterson Ridge 1-20H
API: 05-057-06515



Photo 2. Non reportable spill - stained soil outside of tank battery berm.



Photo 3. Non reportable spill - stained soil outside of tank battery berm.

Inspection Photos
Location Name: Peterson Ridge 1-20H
API: 05-057-06515



Photo 4. Non reportable spill - stained soil outside of tank battery berm.



Photo 5. Non reportable spill - stained soil outside of tank battery berm at loadout.

Inspection Photos
Location Name: Peterson Ridge 1-20H
API: 05-057-06515



Photo 6. Non reportable spill - stained soil outside of tank battery berm.



Photo 7. Non reportable spill - stained soil outside of tank battery berm at loadout.

Inspection Photos
Location Name: Peterson Ridge 1-20H
API: 05-057-06515



Photo 8. Rills coming onto location from northeast perimeter.



Photo 9. Non reportable spill - stained soil on access road outside of location perimeter berm.

Inspection Photos
Location Name: Peterson Ridge 1-20H
API: 05-057-06515



Photo 10. Tracking onto Colorado State Highway 14 going south from location.



Photo 11. Tracking onto Colorado State Highway 14 going north from location.