

Inspection Photos

Loc#436713

Operator: Ursa

Inspection Number: 692400938

Inspection Date: 4/26/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

April 26 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley L Loc#436713



Photo#2:

A few of the Wildlife Escape Boards in cellars are not adjusted properly .

April 26 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley L Loc#436713



Photo#3:
Weeds noted on site.

April 26 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley L Loc#436713