

Final Reclamation Inspection

May 13, 2019

Operator: ANADARKO WATTENBERG OIL COMPLEX LLC -
#10600

Location ID#: 319793

Inspection Document #: 697500136

Adams County, CO

SESE Section 7 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location ID#: 319793



Photo 1. Photo taken from the tank battery location (39.972112, -104.924897), facing East. Riser (red circle) has been left on location. Operator shall remove riser per Rule 1004.a.

Inspection Photos
Location ID#: 319793



Photo 2. Photo taken from the tank battery location, facing Northeast. Debris left on location. This debris appears to be from the removal of the meter run on location. There was other debris observed on location as well. A corrective action has already been issued to remove this debris by 5/28/2019 (Field Inspection Report Doc. #697500130).