

# *Inspection Photos*

*ALs Loc#419862*

*Operator: Terra*

*Inspection Number: 692401010*

*Inspection Date: 5/21/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Six unknown risers at AL Well positions.

May 21, ,2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra ALs Mead Loc#419862





Photo#2:  
Six unknown risers at AL Well positions.

May 21, ,2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra ALs Mead Loc#419862