



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Clay Elkins (celkins@gobrainstorm.net) |
| Submission Date: | May 29, 2019 10:08:29 AM MDT |
| Server Receive Date: | May 29, 2019 12:20:40 PM MDT |
| Reference Number: | 20190529-18107736838 |
| Location: | Unknown Location |

Information

| | |
|-----------------|--------------------------------------|
| Name | celkins@gobrainstorm.net |
| Date | May 28, 2019 |
| Well Name | JOHNSON, MW GAS UNIT A 1 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Other Clean Up Contaminated Soils |

Picture North to South



Picture South to North



Picture East to West



Picture West to East

